

# Hygenall™ **HEXOFF™** Surface Cleaner

## Instructions for use.

**USAGE:** use to clean and decontaminate non-porous surfaces after exposure to heavy metals including Hexavalent Chromium and Cadmium. CM3034



PN: HXLS9001Q

These instructions should be considered as general usage guidance, and may need to be adjusted through experimentation for varying types of surfaces and contamination levels.

5 Gallon (PN: HXLS9005G) and 55 Gallon (PN: HXLS90055G) versions are concentrated, and depending on the amount of Cr(VI) contamination, and type of surface, the formula may be diluted up to 4 parts water to 1 part Hygenall surface solution. As noted above, it is important to experiment and test to achieve best results.



## Safety First

Please follow all directions and warnings on the label, including wearing appropriate safety equipment. Test surfaces in an inconspicuous area to ensure compatibility. **KEEP OUT OF THE REACH OF CHILDREN.**

## Light Dirt and Contamination

Apply generously, wait 5 to 10 seconds, wipe off with damp towel. Avoid letting formula dry on surface.

## Heavy Dirt and Contamination

Spray on surface and let sit for 30 to 60 seconds (with hexavalent chromium, let sit up to 4 minutes).

Avoid allowing formulation to dry on the surface by applying generous amounts.

Scrub with brush or scrubbing pad, rinse with fresh water or wipe surface with a heavily wetted towel.

Repeat as necessary.

Follow an established cleaning schedule using Hygenall cleaning and decontamination products to keep contaminants from accumulating.

If over used, use a damp towel to clean off excess or dried soap on surface.